



AIR CRUISERS - AERAZUR

*Original Manufacturers of
Helicopter Flotation Systems*

- Only mechanically activated system certified for ditching as apposed to emergency landing
- Only mechanically activated system certified for deployment air speeds up to 120kt
- Float kit comes complete with installation hardware
- Simple after-factory installation
- OEM quality at competitive price
- 18 Month maintenance intervals



New EC120

**Mechanically Activated
Emergency Flotation System**





EC120

Mechanically Activated Emergency Flotation System

AIR CRUISERS - AERAZUR

“Rely on the team that sets the standards for reliability and product support.”



Specifications:

Maintenance Interval	18 months
Inflated Buoyancy Rate per System (Fresh Water)	6194 lb (2810 kg)
Inflation Time	2 to 3 seconds
Air Speed/Altitude	Inflight deployment up to 120 kt (138 mph) and altitude of up to 13,200ft (4000m)
Type of Inflation System	High pressure stored gas (Helium) with mechanically activated inflation valve.*
DOT Approved Carbon Composite Reservoir Volume/Pressure	1114 cu in (18.74 L)/ 3500 psig (2412 N/cm ²)
Float and Cover Material	Urethane Coated Nylon
Total System Weight	106 lb (48.1 kg)
Certification	Installation FAA Certified STC / FAA - PMA Approved
Activation Trigger	Available for installation on cyclic or collective control

*Available with optional electrically activated inflation valve.



USA SALES OFFICE :

Air Crusiers Company
P.O. Box 180
Belmar, NJ 07719-0180, USA
Telephone: 732-681-3527
Fax: 732-681-9163
email: info@aircruisers.zodiac.com
www.aircruisers.com

INTERNATIONAL SALES OFFICES:

Aérazur
48 Boulevard Gallieni
92137 Issy-Les-Moulineaux, France
Telephone: 33-1-41 23 23 23
Fax: 33-1-46 48 74 79
www.aerazur.com

Air Cruisers International
Building 140, East Camp
Seletar Airport, Singapore 798379
Telephone: 65-6482 08 89
Fax: 65-6482 09 62

Air Cruisers International
Room 2010
Hua-Ou Aviation Support Center
Tianzhu Airport Industrial Zone
P.O. Box 3412
Shunyi, Beijing 101312
P.R. China
Telephone: 86-10-80486850
Fax: 86-10-80489221